

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 1, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 1, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 30, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 1, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 1, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 12, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #1

## Certificates of Completion

November 6, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 1, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 1, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On October 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

November 6, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 1, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 1, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On October 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 2, Unit 101  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 2, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 15, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CPH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 2, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 2, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 15, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CPH  
Principal Project Manager

JCW/JDG/dd

# Building #2

## Certificates of Completion

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 2, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 2, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 15, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CPH  
Principal Project Manager

JCW/JDG/dd

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 2, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 2, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 30, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CPH  
Principal Project Manager

JCW/JDG/dd

August 25, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 3, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 3, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 25, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 3, Unit 102  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 3, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #3

## Certificates of Completion

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 3, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 3, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 3, Unit 104  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 3, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 4, Unit 101  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 4, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

November 6, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 4, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 4, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On October 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #4

## Certificates of Completion

October 2, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 4, Unit 103  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 4, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 27, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 4, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 4, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 30, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 5, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 5, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 8, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 5, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 5, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 8, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #5

## Certificates of Completion

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 5, Unit 102  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 5, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 30, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 5, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 5, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 25 and 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

**A.G. Wassenaar**

Geotechnical and Environmental Consultants

2180 South Ivanhoe Street, Suite 5  
Denver, Colorado 80222-5710  
303-759-8373 Fax 303-759-4874  
www.agwassenaar.com

August 25, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 6, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 6, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

**A.G. Wassenaar**

Geotechnical and Environmental Consultants

2180 South Ivanhoe Street, Suite 5  
Denver, Colorado 80222-5710  
303-759-8373 Fax 303-759-4874  
www.agwassenaar.com

December 7, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 6, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 6, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On December 7, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #6

## Certificates of Completion

**A.G. Wassenaar**

Geotechnical and Environmental Consultants

2180 South Ivanhoe Street, Suite 5  
Denver, Colorado 80222-5710  
303-759-8373 Fax 303-759-4874  
www.agwassenaar.com

December 7, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 6, Unit 103  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 6, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On December 7, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

**A.G. Wassenaar**

Geotechnical and Environmental Consultants

2180 South Ivanhoe Street, Suite 5  
Denver, Colorado 80222-5710  
303-759-8373 Fax 303-759-4874  
www.agwassenaar.com

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 6, Unit 104  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 6, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joseph C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 7, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:


As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 7, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 8, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CH  
Principal Project Manager

JCW/IDG/dd

October 2, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 7, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:


As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 7, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 27, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CH  
Principal Project Manager

JCW/IDG/dd

## Building #7 Certificates of Completion

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 7, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:


As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 7, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 30, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CH  
Principal Project Manager

JCW/IDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 7, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:


As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 7, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 15, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CH  
Principal Project Manager

JCW/IDG/dd

October 2, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 8, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 8, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 27, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 15, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 8, Unit 102  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:


As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 8, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 8, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

## Building #8 Certificates of Completion

December 7, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 8, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 8, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On December 7, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

July 28, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner

Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 8, Unit 104  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 8, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On July 25 and 28, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.

  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd



November 6, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 9, Unit 101  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 9, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On October 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 9, Unit 102  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 9, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 12, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #9

## Certificates of Completion

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 9, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 9, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 12, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

September 18, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 9, Unit 104  
Denver, Colorado  
Project Number E06131.EC

Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 9, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 12, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
John C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 25, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 10, Unit 101  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 10, Unit 101 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

August 25, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 10, Unit 102  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 10, Unit 102 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On August 23, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

# Building #10

## Certificates of Completion

October 2, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 10, Unit 103  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 10, Unit 103 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 27, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd

October 2, 2006

Four Mile Village Condominium Association  
c/o Wehner Property Management  
280 South Madison Street  
Denver, Colorado 80209

Attention: Mr. Russ Wehner


Subject: Post-Remediation Crawl Space Evaluation (Conformance Evaluation)  
Four Mile Village Condominiums  
Building 10, Unit 104  
Denver, Colorado  
Project Number E06131.EC


Dear Mr. Wehner:

As requested, A. G. Wassenaar, Inc. (AGW) has evaluated the crawlspace associated with Building 10, Unit 104 at the Four Mile Village Condominium complex, located at 540 South Forest Street in Denver, Colorado. This crawl space was evaluated following completion of remediation activities by Select Specialty Services, LLC (Select). On September 27, 2006, AGW conducted an assessment of the post-remediation conditions in the crawlspace of the unit to determine if effective completion of remediation recommendations was performed. This conformance evaluation was scheduled through representatives of Wehner and/or Select, in coordination with the unit resident.

Based on findings from the post-remediation evaluation, it is our opinion that the remedial work in the crawlspace has been completed in general conformance to the recommendations we provided in our initial scope-of-work report for the property, dated February 13, 2006. No visible mold was identified to be present during our conformance evaluation, and the condition of the crawlspace at the time of the post-remediation evaluation was commensurate with current construction practices for spaces of this type.

Thank you for the opportunity to work with you on this project. If you have any questions or require additional information, please do not hesitate to call.

Sincerely,  
A. G. WASSENAAR, INC.
  
Joan C. Wickersheim  
Senior Industrial Hygienist

  
Joseph D. Gifford, CIH  
Principal Project Manager

JCW/JDG/dd